

BILL OF MATERIALS

Procurement of Supply and Delivery of Services for Labor and Materials for the Repair and Maintenance of R. P Vehicle Isuzu Crosswind with Plate No. SJU-427 assigned at RAED and Supply and Delivery of Tires and Automotive Battery of RP Vehicle Isuzu Elf Truck with Plate No. SKZ - 190 assigned at Research Division.

Unit	Item Description	Quantity	Unit Cost	Total Cost
	Isuzu Crosswind with Plate No. SJU-427			
Pieces	Tie rod end Lh/Rh Inner and Outer	4		
Piece	Ball joint Upper and Lower Lh/Rh	4		
Pieces	Suspension Bushing Upper and Lh/Rh	4		
Pieces	Suspension Spring Bushing Upper Lh/Rh	2		
Pieces	Suspension Spring Bushing Lower Lh/Rh	4		
Pieces	Stabilizer Bushing Lh/Rh	2		
Piece	Idle arm	1		
Pieces	Front shock absorber Lh/Rh	2		
Piece	Center link	1		
Piece	Air filter	1		
Piece	Fuel filter	1		
Pieces	Air con belt	2		
Piece	Alternator belt	1		
Set	Injection pump repair kit (Fuel Pump)	1		
Set	Floor matting	1		
Liter	Diesel Fuel	30		
Labor	Fuel tank pulldown and cleaning	1		
Labor	EGR cleaning and intake cleaning	1		
Labor	Injector pump calibration	1		
Labor	Wheel alignment	1		
	Isuzu Elf Truck with Plate No. SKZ - 190			
Pieces	Tires, 7.50 x R 16, 12 Ply	6		
Pieces	Exterior Tires 7.50 x R 16	6		
Pieces	Tire Flat, 7.50 x R 16	6		
Units	Automotive Battery 11, Plate, 12 volts	2		
	Maintenance Free, Heavy Duty			
	Total			